# भारत सरकार GOVERNMENT OF INDIA रेल मंत्रालय MINISTRY OF RAILWAYS (रेलवे बोर्ड RAILWAY BOARD)

## No. 2007/ M(C)/137/16/Vol (ix) Part

### New Delhi dated of .03.2017

### Chief Mechanical Engineers (All Indian Railways)

### Sub: Breakage of Springs of FIAT Bogies

Ref: 1. ED / Carriage / RDSO's letter No. SV FIAT Spring dated 30.01.2017.

2. CQM / RCFK's letter No.MTQ/12004 dated 25.01.2017

CME/NR has reported an alarming number of cases of coil spring breakage of FIAT bogies. Similar failures have been reported by the other Railways too.

As per the analysis carried out by RCFK and RDSO, most of failed springs pertain to a specific manufacturer, i.e. M/s LPDN Germany. In this regard, RCF vide their letter at reference 2 have advised the Railways to replace the secondary outer springs of LPDN 2012 make as early as possible. The list of coaches / bogies fitted with these springs has been enclosed along with RCF's letter. A committee of CQM/RCFK, DME/Chg/RB, Director/Carriage/RDSO, Sr.DME/Chg/NDLS and Sr.CDO/BCT has also carried out investigation in this matter and their report is enclosed for information.

The Railways are advised to take necessary action of replacing the secondary outer springs of LPDN 2012 make as suggested by RCF and the Committee. RCFK shall supply additional springs to the Railways for carrying out the replacement. The released springs of LPDN 2012 make shall be returned to RCF by the Railways for taking up the matter with the supplier.

The Railways are also advised to scrupulously comply with the maintenance instructions for flexi coil springs in FIAT bogies of LHB coaches circulated vide RDSO's letter at reference 1.

ی کی کی (Shailendra Singh) (Executive Dir. Mech. Engg. (Chg.) Railway Board

Copy to

**Chief Mechanical Engineer, RCFK :** RCFK shall expeditiously supply additional springs for replacement to the Railways. They shall also raise this issue with M/s LPDN and take action, as deemed appropriate.

#### ED/Carriage/RDSO





णासः। सारकार - रेल मंत्रालग अनुसंधान अभिदाला और पानक संघठन लखनरऊ - 226 011 . EFBX (0522) 24512 Fax (0522) 2458500 Government of India-Ministry of Raliways Research Designs & Standards Organisation Lucknow - 226 011 DID (0522) 2450115 DID (0522) 2465310



No:SV.FIAT Spring

Dated:- 30.01.2017

CMEs, All Indian Railways & Production Units

Sub: - Maintenance instructions for flexi coil springs in FIAT bogies of LHB coaches.

Ref:- This office letters of even no. dated 08-12-14, 16-07-15 & 04-01-2017.

Zonal Railways have reported failure of flexi coil springs in FIAT bogies of LHB coaches. The trend in this reporting has suddenly shown a spurt in December 2016 and January 2017. Remedial measures have been suggested from time to time as indicated in the reference. In order to ensure that the latest preventive measures are to be taken into practice, efforts have been made to compile the maintenance instructions with the idea of making it at a single point reference for coil springs in FIAT bogies of LHB coaches. Copy of CMI is enclosed herewith for implementation in the field. It is requested that feedback and suggestion may be given for further improvement in CMI, based on the experience gained in field so that all possible preventive actions are taken to ensure the best maintenance practices implemented and failures in open line avoided

DA: As above

(Indrajit Singh) Executive Director/Carriage

Copy to:

AM/PU, Railway Board, New Delhi
 AM/ME, Railway Board, New Delhi

for information please.

3. EDME/Coaching, Railway Board, New Delhi

4. ED/CAMTECH, Gwalior : for incorporation in CAMTECH manual.

# RAIL COACH FACTORY (KAPURTHALA)

Dated: 25/01/2017

CN A.

No: MTQ/12004

Director Mech Engg (Coaching) Railway Board Rail Bhawan New Delhi - 110 001

Sub:

211

Breakage of springs of FIAT Bogies of Gatistian/Rajdhani/Shatabdi trains.

Ref: 1) Your letter no. 2007/M(C)/137/16/Vol(ix)Part dated 03/01/2017.
2) This office letter no. MTQ/12004 dated 09/01/2017.

This is in continuation to our letter referred #2 above, wherein details of the coaches/bogies fitted with LPDN 2012 make secondary outer springs were advised in two annexures; Annexure-II containing coach number on which such springs were titted and Annxure-III containing serial number of bogies whose coach numbers were not available at that time.

The details of the coaches/bogies fitted with LPDN 2012 make secondary outer springs have now been collected and the final list is enclosed. This list contains 317 records. Some bogies were given separately to Railway/PUs 'B' is mentioned with the bogic number given in 'Coach/Bogic number' column for such cases. The earlier figure of 331 coaches stands correct as some double and incorrect rows have been deleted.

As mentioned earlier, it is advisable to change secondary outer springs of LPDN 2012 make as early as possible.

(B. Attri) Chief Quality Manager For Chief Mechanical Engineer

Capy to:

1. All CMEs of Zonal Railways

2. CME/ICF/Chennai

3. CME/MCF/RBL

May kindly advise the concerned railways to whom the bogies mentioned in the attached list have been supplied for necessary action.

myestigator as to the increase in the fallenes of

# 中自由的规则的制度

There has been an alaming increase in the failure of tHB Commentas per the histingious of Religing Roard, an imposignition has been consider the same was condiad and by the team comprising of COAVECCER. DME/Coschino/R8. र के Director/Granksge/RDSG. STALLOGITI SITE DY.COMPROFE of MEXIS Slok Line on 13.1.18 & 14.1.16. CRSE/CoopHR. DY OME/Cog. AND & SECTIME/MOLS TWATE also preventionly present during the 的历史和自己的

# 20 Data of Spring Failures

The data collected from the Railways is attached in Annexure A. As per data available with RDGO, most of the failures reported to them pertain to LPDH spanes of 2012 batch. Many of these springs have been fitted by RCFK in ocaches turned

out in 2016 & 2016.

S. O Ghservations of Coaches at NDLS Sick line

A total of five conches were inspected at NDLS Sick line on 13 1,17 & 14 | 17. The detailed observations sheets and attached as Annexine 5. The summary of custors inspected and the main discrepancies noticed are sumparized below:

b. 153877 NR LWSCZAC:Gatimun coach, RCF in which one spring had been

- c. 153901 NR LWOBAC: RCF coach in which one spring had been replaced on
- · 11.1.17 The height of the two Secondary springs on one bogie as indicated on the copper band were 509mm and 503mm. Let a difference of 6mm (which is d. 153128 NR LWACCN: RBL coach. Copper band were not available in on one of
- e. By and large the pairing and orientation of the springs was as presented (avcept).
- for a slight discrepancy in the height of the two secondary springs in coach No.153801 NR LMCBAC). 8. Shifting of one spring was noticed in the dome of bolstor of Coach Ho. 1535.77 L. Dust and Muck was observed on the springs.
- (Boyle No. 156500). The spring had been replaced at Agra

4.0 Observations of failed Stainus at NDLS Stelling

Barrer

1411

A total of 8 broken secondary springs and one primary spring available in the Stok line were inspected. The observations are attached as Annexure C. The main observations are summarized below:

- a. Most of the springs had failed because of fatigue initiated from corrosion pilting.
- b. The springs has broken from the bottom portion. The location of failure was just before or just after the first coil (in four springs, it was after the completion of the first coil, and in two cases it was just before the completion of the first coll). The latter two cases shall be investigated in detail by RDSO, as breakage before the completion of the first coll is not normally seen.
- c. RDSO informed that ghost lines of austenite grams were found towards the core region of the spring cross section as against the requirement of tempered martensite in some of the failed springs of LPIDNmakethat were tested in RDSO. The increased failures of LPDN springs may also be due to phosphating not being done by LPDM.

#### 8.0 Action by RGFK:

- n. RCF shall issue a list of the 331 coaches that have been filled with LPDF1 make springs of 2012 betch to the Kalways. RCF shall supply replacement optings to the depois. The Depois shall replace the LPDN 2012 springs filled in coaches. RCFK may also consider providing manpower assistance to the extent feasible. especially for the Depots that have a large holding of such coaches. COM/RCF informed that letter and email has been sent to all concerned railways giving. details of 192 coaches filled with these springs. Information regarding balance 139 coaches shall be given soon.
- b. RCF shall take up the matter with LPDN, who shall be asked to replace the springs of 2012 batch free of cost. RCF shall also take other action as deemed necessary against this vendor.
- c. RCFK shall look into the reasons for using these springs after many years of supply and address the systemic deliciencies.
- d. RCKF shall lake necessary action to ensure that springs conforming to the specifications are accepted.

### 6.0 Action by RDSO

- a. RDSO shall issue the consolidated list of instructions for Depot & Workshops which shall also be included in the CAMTECH Manual by issue of Correction Slips.
- 5. ROSO wide letter dated 5/12/14 had stated that the direction of alignment deviation in new springs of Grueber and LPDN was 180 degree apart This is Skely to introduce error in filment. Though RCF have reported that the losse was resolved with LPDM alter 2014. this needs to be checked during loan resting in

2 ļ

ther\_ 1411

the workshops and the objectment hand is to be provided massedly. Underm restructions an itiment of springs, irrespective of make, need to be issued to the Dents

CRSE this pointed our that washing of springs/bogle with high pressure water jet and subsequent drying as advised by RDSO is not feasible in the D-1 / D-2 or D-3 Schedules carried out at pit line. RDSO shall examine if allemate method of cleaning of springs such as air blowing is feasible. For this, compressor / Mine

line with tapping at each coach location shall have to be provided on the pit lines. d. A significant No. of failures have been reported of RSK springs also: ED Carilage

- RDSC may issue a specification for the indigenous make springs (including RSK) and ED QA Mechanical RDSO should carryout purchase inspection of bolly new material as well as finished springs for LHE coaches, that are purchased from indigenous sources (including RSK).
- e. Based on the data received from the Railways. RDSO shall upload an analysis of spring failure cases, every month on RDSO website. The format for data connection shall include the make of inner /cater springs, lateral and longituded bump stop clostencos, issues of funcent, investigation varied can by Ratemys  $\leq \frac{2}{3} \langle \psi \rangle$
- t. RDSO shull investigate if there is a conclusion between the spring failures and CARLE TO DESCRIPTION.
- o. The testic of quality of most was declarable. The existing specification prevented by RDSO (IS 12744:1983 for primer and IS 3862:2004 for top coat) may not be justion till the next shop astmoute after which re-painting has been presented. A for hading paint monthelinens any be used to suggest the proper painting scheme for the opringe conforming to the bload requirements given in the FIAT specification (no. 17.248). Triple with these points should be carried out in the new springs manufactured of RSK. Simultaneously, M&C Die, of RDSO shall develop a proper specification for the paint of springs on that it can last between suscessive stops concerned.

# 7.0 Action for Denote a Visio Laboration

- As per practice of filled sink find Life constant ore being liked hore one the applicate entries also bound to extrapolytics househing of this spatinger to addition points Singlements litting of weethes from both sides as presented in UR manual
- 5. The practices of spring bondling due need to be improved. Proper terralities, storage and comparishin of springe medic to the construct, stated to your contact status spring functing, fifting, colling of springs on the grand, so star result in paint prefing off, which may lead to failures.

1411

- The hardware (mas) used is bogic assauldy should be renewed once they are opened due to any reason as they are provailing lorque type meant for single use.
- d. Depots have reported that it is not feasible to carry out and attend the springs as per Para C(i) of RDSO's letter dated 16/7/2015 in the pit lines, and that coaches may have to be detached for proper spring attention / repair. In order to get an idea as to the extent of the problem, a 15 days drive shall be carried out in the Depots as per format included as Annexure D. Spring fitment issues shall also be looked into during the drive.
- Whenever every coach is detached in the Depots for out of course repairs that require coach lifting, the springs shall mandatorily be attended and paint damage attended as per Para C (i) of RDSO's letter dated 16/7/2015 (only paint touch work, particularly in the contact zone, is to be done in the Depots. In case complete spring painting is required, the same shall be done in the Workshops).
- Records for the springs filled in coaches shall be runinizined and mobilitied by the Depots.
- g. It has been reported that the local testing machines are not operational/ available at some of the Workshops. This needs to be ensured. RDSO shall audit the maintenance practices of LHB springs at a few W/s and give a report that the attention as per RDSO's lotter dated 16/7/2015, reiterated on 4.1.15 is being given. The workshops shall take corrective / preventive actions based on these audits.
- h. As per data maintained by BCT depot (Annexure E). there is an increase in the rate of spring failure after a life of 6 years. Therefore, the feasibility of replacing springs in the SS3 Schedule (6 years / 24 Lac Km, whichever is earlier) may be examined by RDSC.

COMRC Sr. DMERCOUNDOSAR (DME/Continu/RB) Directork ISI.GDO/BCT/MR OMROFKI