


Presentation on AAR type H-type tight lock Center buffer coupler






CBC height, must be from 1230 mm to 1245 mm (to be taken from rail level to top of the knuckle) knuckle height is 280 mm










Complete fitment of CBC

Ensure proper condition & functioning of CBC's manual uncoupling device and its





piece




- a. Tell-Tale sign. Inverted 'V' should be clear of obstruction
- b. Rotary lever in vertical position
- c. Cross pin (Diameter-18 mm) to ensure full coupling of CBC




Ensure proper condition of supporting device for its securing fastenings




Key for opening of manual uncoupling device Locking mechanism is provided for operating lever to ensure perfect locking of operating rod.









Double rotary lift assembly




Knuckle mating surface




For changing of shim 36 mm in SLRs box spanner is required









CBC central pin supporting base plate and tighten with 16x50 mm nut and bolt (use 24 mm spanner)



CBC draft gear support plate and tighten with 16x50 mm nut and bolt (use 24 mm socket spanner)










Preloaded compression springs, FTIL make (to be checked) and special type Allen bolt must be checked).


14 mm allen key & 19 mm socket spanner is required for FTIL Make.

17 mm allen key & 24 mm socket spanner is required for Escort Make



CBC supporting device to be opened by 30 mm box spanner with torque wrench (450± N-m)







During coupling of CBC it must ensure position of CBC, it must be in center position and coupling of CBC should not be done in the curvature of track



Difference of height between CBC's more than 75 mm is not allowed

Don'ts

Do not apply grease on parts like lock, lock lift assembly, and knuckle.

Do not hammer lock lift assembly.

Do not tie rotary lever and operating lever hook with binding wire.





CBC Central pin base plate along with axial stiffner plate punctured



Central pin base plate and axial stiffener plate shown separately. The punctured hole on axial stiffener plate matching with existing hole on base plate allowing central pin to drop down wards causing coupler body to come out and parting.



Parting took place towards CEN end of the coach where the axial stiffener plate fully punctured and a hole formed. The axial stiffener plate on VSKP end of the coach also removed for inspection. It may be seen that the development of hole is in the formative stage due to rubbing and hitting of yoke pin which is a potential case for parting.





The silent block bush of coupler body CEN end of coach rubber bonding is completely given up due to which sleeve worked out as shown above.

The silent block of coupler body VSKP end also given up partially as shown above.