

# **MILLING MACHINES**

BY

**S.SRIKRISHNA**

Sr.Lecturer, STC/SC

# MILLING

- **Milling:** is the process of removing metal by feeding the work against a rotating multi point cutter.
- In milling operation the rate of metal removal is rapid as the cutter rotates at a high speed and has many cutting edges.
- The machine can also hold one or more cutters at a time.
- It is the most versatile of all machine tools.
- Flat or formed surfaces may be machined with excellent finish and great accuracy.
- It is designed for machining a variety of tool room work

# TYPES OF MILLING MACHINES

- Types of milling machines: According to the design and construction they are classified as follows

## I. Column and Knee type

1. Hand milling machine
2. Plain milling machine
3. Universal milling machine
4. Omniversal milling machine
5. Vertical milling machine

## II. Planer milling machine


## III. Fixed bed type

1. Simplex milling machine
2. Duplex milling machine
3. Triplex milling machine

## IV. Special types:

1. Rotary table milling machine
2. Drum milling machine
2. Planetary milling machine
3. Duplicating milling machine
5. Profile milling machine

# TYPES OF MILLING MACHINES



**Figure 11.1 Column and knee type milling machine**  
1. Base, 2. Elevating screw, 3. Knee, 4. Knee elevating handle, 5. Crossfeed handle, 6. Saddle, Table, 8. Front brace, 9. Arbor support, 10. Cone pulley, 15. Telescopic feed shaft.

# TYPES OF MILLING MACHINES



Simplex Milling machine



Duplex Milling machine



Triplex Milling machine



Drum Milling machine



Planetary Milling machine

# TYPES OF MILLING MACHINES



Rotary Milling machine



Rotary Milling attachment



Rotary Milling Operation



Profile Milling Machine



# SIZE OF MILLING MACHINE

## 2.4 SIZE OF MILLING MACHINE :

The size of the column and knee type milling machine is designated by the dimensions of the working surface of the table and its maximum length of longitudinal, cross and vertical travel of the table. The following are the typical size of a horizontal knee type milling machine.

Table length  $\times$  width = 1100  $\times$  310 mm.

Power traverse = longitudinal  $\times$  cross  $\times$  vertical  
= 650  $\times$  235  $\times$  420 mm.

In addition to the above dimensions, number of spindle speeds, number feeds, spindle nose taper, power available, net weight and the floor space required, etc. should also be stated in order to specify the machine fully.

# MILLING MACHINE OPERATIONS

## 2.5 MILLING OPERATIONS :


The following are the different operations performed in a milling machine

1. Plain milling
2. Face milling
3. Form milling
4. Straddle milling
5. Angular milling
6. Gang milling
7. Profile milling
8. End milling
9. Helical milling
10. Gear cutting



# MILLING MACHINE OPERATIONS

1. **Plain or slab or peripheral milling** : It is the operation of production of a plain, flat, horizontal surface parallel to




1. Slab mill

2. Work

Fig. 2.3. Slab Milling


# MILLING MACHINE OPERATIONS



1. Face milling cutter    2. Work

Fig. 2.4. Face milling


# MILLING MACHINE OPERATIONS



1. Formed cutter      2. Work

Fig. 2.5. Form Milling


# MILLING MACHINE OPERATIONS



1. Straddle cutter      2. Work


Fig. 2.6. Straddle milling

# MILLING MACHINE OPERATIONS



**Fig. 2.8. Gang Milling**

# MILLING MACHINE OPERATIONS



- |   |             |
|---|-------------|
| 1. Power connection between tool and tracer |             |
| 2. Contoured profile                        | 3. Tracer   |
| 4. Master die                               | 5. Table    |
| 6. Work                                     | 7. End mill |

**Fig. 2.9. Profile Milling**

# Indexing

Indexing: The indexing is the operation of dividing the periphery of a work piece into any number of equal parts

In cutting spur gear, equal spacing of teeth on the gear blank is performed by indexing.

Indexing required for producing


- 1.Hexagonal and Square head bolts
- 2.Cutting splines on shafts
- 3.Fluting drills, taps and reamers etc.

Indexing is accomplished by using a special attachment known as Dividing Head or Indexing Head

1. Plain or Simple indexing head
2. Universal dividing head
3. Optical dividing head

# Indexing Methods

1. Direct or Rapid indexing
2. Plain or simple indexing
3. Compound indexing
4. Differential Indexing
5. Angular Indexing





# Indexing Methods

**Rule for direct indexing :** To find the index movement, divide the total number of holes in the direct index plate by the number of divisions required on the work. In this case, when the direct index plate has 24 holes, the formula for indexing is given below :

$$\text{No. of holes to be moved} = \frac{24}{N} \quad 12.1$$


Where,  $N$  = number of divisions required

**Example 12.1 :** Find out the index movement required to mill a hexagonal bolt by direct indexing. The rapid index plate has 24 holes.

$$\text{No. of holes to be moved} = \frac{24}{6} = 4$$

After machining one side of the bolt the index plate will have to be moved by 4 holes for 5 number of times to machine the remaining faces of the bolt.

# Indexing Methods



- |               |                |         |
|---------------|----------------|---------|
| 1. Worm wheel | 2. Spindle     | 3. Dog  |
| 4. Job        | 5. Index plate | 6. Worm |
| 7. Worm shaft | 8. Crank pin   |         |

Fig. 2.35 Plain Indexing

# Indexing Methods

The index plate has several circles with different number of holes in each circle. The standard Brown and sharp index plates have the following circles.

Plate No. 1—-----15, 16, 17, 18, 19, 20.

Plate No 2—-----21, 23, 27, 29, 31, 33.

Plate No. 3—-----37, 39, 41, 43, 47, 49.

With the above three index plates simple indexing can be used for all divisions up to 50, even numbers upto 100, except 96, and many others.

**Rule :** The index crank movement =  $\frac{40}{N}$  where N is the number of divisions required.

**Example (2.2) :** Find out the index movement to mill 25 teeth on a spur wheel blank. Index crank movement =  $\frac{40}{25} = 1\frac{3}{5} \times \frac{3}{3} = 1\frac{9}{15}$ . Thus for indexing, one complete revolution and 9 holes in 15 holes circle of the index plate will be moved by the index crank.

# Indexing Methods