भारत सरकार GOVERNMENT OF INDIA रेल मंत्रालय MINISTRY OF RAILWAYS (रेलवे बोर्ड RAILWAY BOARD)

No.99/M(C)/141/21

New Delhi, dt. 5.03.2015

Chief Mechanical Engineers, All Indian Railways. RCF, Kapurthala, RCF, Rae Bareli and ICF, Chennai.

Managing Director, BEML, Bangaluru.

Sub: Provision of dustbin in Non-AC coaches under Mission 'Swachh

Bharat Abhiyan'.

Ref: i) Board's letter of even No. dated 20.11.2014.

ii) RDSO's letter No.MC/CB/LF dated 17.02.2015.

Reference above. Vide Board's letter referred at (i) above, ICF, RCF/KXH, RCF/RBL and BEML were advised to provide suitable dustbins with pedal operated lid opening mechanism below the outside wash basin in all newly manufactured coaches. while PUs were also advised to issue Carriage Alteration Instructions for retrofitment of dustbins in Non-AC coaches by the Zonal Railways for different design of coaches already in service and without such provisions.

The progress made in this direction has been reviewed in Board and it has been decided that PUs and Railways should take immediate action for implementation of above instructions with the existing design of dustbins.

Meanwhile, Design improvements and standardization in design of dustbins can be taken up concurrently by PUs and RDSO for future.

(Prashant Kumar)
Director Mech. Engg. (Coaching)
Railway Board

Copy to:

ED/Carriage, RDSO/Lucknow.